

---

# NOTICE TO MARINERS

---

**No. H. 121/2025**

## **R I V E R   H U M B E R**

### **HUMBER LIGHT FLOAT RETURNED TO STATION**

**MARINERS ARE ADVISED** that the Humber Light Float has been returned to its original charted position:

The green mono-hull light float exhibits the following characteristics:

Latitude: 53° 38.700' N      Longitude: 0° 21.240' E

Characteristics: LFl.G.10s

Racon (T)

AIS Name: HUMBER LIGHT FLOAT

MMSI: 992351174

**MARINERS ARE FURTHER ADVISED** that the temporary buoy has been removed and that Notice to Mariners No. H.36/2025 is hereby cancelled.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

9<sup>th</sup> September 2025

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)