

---

# NOTICE TO MARINERS

---

No. H. 136/2025

## RIVER HUMBER

### SOUTH EAST CHEQUER FLOAT TEMPORARY REPLACEMENT

**MARINERS ARE ADVISED** that the South East Chequer Float has been replaced with a temporary floating mark. Until further notice, a buoy is being used as a temporary replacement in its charted position (see details below):

- Position – 53° 33.358' N, 0° 12.860' E (WGS84)
- Light Characteristic – VQ(6)+LFL.10s
- South Cardinal Buoy

**MARINERS ARE FURTHER ADVISED** that the Virtual Aid to Navigation broadcast by AIS as per Notice to Mariners No. H.132/2025 has been discontinued.

The original float will be repaired and returned to station as soon as circumstances permit.

**MARINERS ARE ADVISED** that Notice to Mariners No. H.131/2025 is hereby cancelled.

**CAPT. A. FIRMAN**  
**HARBOUR MASTER, HUMBER**

25<sup>th</sup> September 2025

#### THE INTERNET

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.  
[www.humber.com](http://www.humber.com)

H. 136/2025  
Page 1 of 1