

---

# NOTICE TO MARINERS

---

**No. H. 172/2025**

## **RIVER HUMBER**

### **HULL ROADS – EAST MIDDLE - SHOAL WATER**

**MARINERS ARE WARNED** that a surveys carried out on the 3<sup>rd</sup> December 2025 shows the following: -

- 1) Depths of between 4.5 metres and 5.5 metres below Chart Datum have encroached up to 18 metres into the Northern edge of the channel from the No. 21 Hebbles Light Buoy to 350 metres upstream of the No. 21 Hebbles Light Buoy.

Deeper water exists to the South in this vicinity.

- 2) Depths of between 4.9 metres and 5.5 metres below Chart Datum have encroached up to 65 metres into the Southern edge of the channel from 185 metres downstream of the East Middle Light Buoy to 120 metres downstream of the No. 22 Hook Light Buoy.

Deeper water exists to the North in this vicinity.

- 3) Depths of between 4.6 metres and 5.5 metres below Chart Datum have encroached up to 72 metres into the Southern edge of the channel from 700 metres downstream to 120 metres upstream of the No. 24 Lower West Middle Light Buoy.

Deeper water exists to the North in this vicinity.

**MARINERS ARE ADVISED** that Notice to Mariners No. H. 144/2025 is hereby cancelled and that the shoal water referred to in Notice to Mariners No. H. 118/2025 is no longer valid.

**CAPT. A. FIRMAN  
HARBOUR MASTER, HUMBER**

4<sup>th</sup> December 2025

**THE INTERNET**

In order to widen communication between ABP Humber Estuary Services and those with an interest in the estuary, you are invited to visit our website which carries a wide range of information, including current live weather and Buoy positions, charts, tidal information and copies of this and other Notice to Mariners.

[www.humber.com](http://www.humber.com)

H. 172/2025  
Page 1 of 1